

HP 34401A MULTIMETER

Produced by

GMI Engineering & Management Institute

&

Hewlett-Packard Company


HP 34401A Multimeter


- ◆ 6 1/2 digit, high performance digital multimeter
- ◆ AC/DC voltage measurements
- ◆ AC/DC current measurements
- ◆ 2 and 4 wire resistance measurements
- ◆ Frequency and Period measurements
- ◆ Math functions

Safety Tips

Protect Yourself:
Avoid contact with Voltage or Current Source.

- 1) Use shrouded test leads and alligator clips.
- 2) Connect leads to multimeter first.
- 3) Do all normal connect/disconnect at source.
- 4) Familiarize yourself with the manual.





Safety Tips

Protect Instrument

- 1) Inductive Devices (e.g. transformers, chokes/inductors) induce very high transient voltages.
- 2) Measuring resistance: Avoid contacting probes with live circuits when in resistance modes.
- 3) Measuring Current: Do not connect probes across voltage source.


Starting Multimeter

- ◆ *To perform a complete self-test, hold down the **shift** key for more than five seconds as you turn on the multimeter.*
- ◆ *The display will indicate whether test passed. Error messages will be displayed if a failure occurs.*

000.002 mVDC

Menu at a Glance

Menu is organized
in a top-down tree
structure with 3 levels



To turn on menu **Shift** **On/Off**

To move left or right



To move up or down



To enter command



A: Meas Menu ➔ **B: Math Menu** ➔ **C: Trig Menu** ➔ **D: Sys Menu** ➔ **E: I/O Menu** ➔ **F: Cal Menu**

1: AC Filter 2:Continuity ➔

1: Min-Max ➔

1: Read Hold ➔

1: RDGS Store ➔

1: HP-IB ADDR ➔

1: Secured ➔

Math Functions

To make null (relative) measurement

Null

To store min/max readings

Min
Max

To make dB measurements

Shift

dB

$$dB = \text{reading in } dBm - \text{relative value in } dBm$$

To make dBm measurements

Shift

dBm

$$dBm = 10 * \log_{10} (\text{reading}^2 / \text{reference resistance} / 1mW)$$

Limit testing (Access through Menu)

Triggering


Auto-trigger: Continuously takes readings at fastest rate possible for present configuration. Default.

Single trigger: Manual trigger by pressing **Single**
One reading or specified number of readings (Sample count).

Number of samples: Number of readings meter takes with each trigger: 1 to 50,000. Default is 1.

Reading hold: Select by pressing **Shift** **Auto/Hold**
Captures and holds a stable reading on the display.

Measuring DC Voltage



* Note measurement indicates only DC portion of signal

Range and Resolution

<u>Range</u>	100 mV	1 V	10 V	100 V	1000 V (750 VAC)
<u>Maximum Resolution</u>	100 nV	1 μ V	10 μ V	100 μ V	1 mV (750 μ VAC)

Resolution Choices & Integration Time

Integration Time**

Resolution Choices

Default →

.02	PLC	Fast 4 Digit	Fastest, Least Accurate
.2	PLC	Fast 5 Digit	
1	PLC	* Slow 4 Digit	
10	PLC	* Slow 5 Digit * Fast 6 Digit	
100	PLC	Slow 6 Digit	Slowest, Most Accurate


* Equivalent to Pressing “Digits” key on front panel.

**In Power Line Cycles (PLC).

Integration times of .02 and .2 do not provide power-line noise rejection characteristics.

Measuring AC Voltage

AC to DC conversion:
DCV proportional to AC RMS



* Note measurement indicates only the AC portion of signal



AC Filter

<u>Frequency</u>	<u>Range*</u>	<u>Time to settle</u>
3 Hz and above	Slow	7 sec.
20 Hz and above	Medium	1 sec.
200 Hz and above	Fast	0.1 sec.

*Selectable through the measurement menu



AC-Coupling vs. DC-Coupling

AC-Coupling-Advantage



*Removes DC Portion of Signal

AC-Coupling-Disadvantage



*Low Frequency waveforms can be cut-off

V_{rms}: Root-Mean-Square

- ◆ Instantaneous power to a resistor is: $P = \frac{v(t)^2}{R}$
- ◆ Average power to a resistor is:

$$P_{avg} = \frac{V_{rms}^2}{R} = \frac{1}{R} \left(\frac{1}{T} \int_{t_0}^{t_0+T} v(t)^2 dt \right)$$


Solving
for V_{rms}:

$$V_{rms} = \sqrt{\frac{1}{T} \int_{t_0}^{t_0+T} v(t)^2 dt}$$

- ◆ A given V_{rms} AC has the heating (power) effect of a VDC with the same value.

Voltage measurements

Peak to Peak



$$V_{rms} = V_p * .707 \text{ (Sine wave)}$$

Measuring Current

$$I = \frac{\Delta V}{r}$$



1.000000 ADC

SHIFT **DC I** = Measure DCI

SHIFT **AC I** = Measure ACI

* **NEVER HOOK CURRENT LEADS**
DIRECTLY ACROSS A VOLTAGE SOURCE


Internal current shunt
(same for ac and dc)



Break circuit to
measure I

Measuring Resistance 2-wire

1.000000 k Ω




- * Press Ω 2W
- * Resistance measured includes lead resistance

*To eliminate the lead resistance:

- Short leads together
- Press NULL
- Lead resistance will be subtracted from reading

Measuring Resistance 4-wire




* Turn off "Null"

* Press SHIFT **Ω4W**

* No error due to lead resistance


4-Wire Resistor Measurement




$$\Delta V = I_{\text{test}} * R$$

$$R = \frac{\Delta V}{I_{\text{test}}}$$


Continuity Test & Diode Check



Cont = Continuity test

Shift  = Diode check


Measuring Frequency & Period



Freq = Measure Frequency

Shift **Period** = Measure Period


Frequency and Period



$$\text{Frequency} = 1/\text{Period}$$

Ratio Measurements

DCV : DCV



$$\text{Ratio} = \frac{\text{dc signal voltage}}{\text{dc reference voltage}}$$


*To enable ratio measurements, use the MEAS menu.

Voltage RMS vs. Peak

<u>Waveform</u>	<u>V_{rms}</u>	<u>V_p</u>
sine	1.0	1.414
triangle	1.0	1.733
square	1.0	1.0
DC	1.0	1.0

* Peak voltage = 1/2 of Peak to Peak voltage

High Z Termination




$$V_s = \left(1 + \frac{R_o}{Z_{in}} \right) * V_m \quad \dots \dots \text{for very large } Z_{in}, V_s \approx V_m$$

As frequency increases, Z_{in} decreases


For less than 1% error $Z_{in} \geq 100 R_o$

50Ω Termination

SIGNAL SOURCE



MEASURING DEVICE



$$V_s = \left(1 + \frac{50\Omega}{50\Omega}\right) * V_m$$

$$V_s = 2 * V_m$$

$$V_m = \left(\frac{1}{2}\right) * V_s$$

*Vm will not equal Vs, if $Z_{in} = R_o$, but the ratio between them is 2:1.

Remote Interface

HP-IB (IEEE-488) Address:

Can be any value between 0 - 31. Factory set at 21.
Address 31 is talk only mode.
Adjustable only through the I/O menu.

RS-232 Interface:

Baud rate must be selected (I/O menu): 300, 600, 1200, 2400, 4800, or 9600.
Parity selection (I/O menu): Even or Odd

Programming Languages

SCPI Language

HP 3478A Language

Fluke 8840A Language

HP-IB




RS-232



Not allowed

Not allowed

Loading Errors (DC volts)




V_s = ideal DUT voltage

R_s = DUT source resistance

R_i = multimeter input resistance
($10 \text{ M}\Omega$ or $> 10 \text{ G}\Omega$)

$$\text{Error}(\%) = \frac{100 * R_s}{R_s + R_i}$$

Leakage Current Errors




I_b = multimeter bias current

R_s = DUT source resistance

C_i = multimeter input capacitance

$$\text{Error}(v) \approx I_b * R_s$$

Common Mode Rejection (CMR)




V_f = float voltage

R_s = DUT source resistance
imbalance

R_i = multimeter isolation
resistance

$$\text{Error}(v) = \frac{V_f * R_s}{R_s + R_i}$$

Noise caused by Ground Loops



R_I = lead resistance

R_i = multimeter isolation resistance

V_{ground} = voltage drop on ground bus

The DIGITAL MULTIMETER

Hints for Accurate Measurements:

- ❖ Measure as near full scale as possible
- ❖ Use a Ratio measurement whenever possible.
- ❖ Before measuring, short the test leads together to check for offsets.
(Exception: RMS AC measurements)

Where to get more information

- ◆ HP 34401A User's Guide
- ◆ HP 34401A Service Guide
- ◆ For on-line technical information call HP Direct at 1-800-452-4844